

**Work Order ID 64120**

November 24, 2010 3:06:47 PM



Page 1

Item ID: D206-642-247

Accept



Setup Start



Revision ID:

Item Name: Wearshoe

Stop



Start Date: 11/24/10 Start Qty: 1.00



Cust Item ID:

Required Date: 11/25/10 Req'd Qty: 1.00



Customer:

Reference: RA110121

V-RETURN

Approvals: Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID	Operation Description
--------------------------------	--------------------------

Draw Nbr	Revision Nbr
----------	--------------

DSI 9466	Rev A
IIN D206-642	Rev N

100



DC

Document Control

Memo

Photocopy bluefile and create labels per PPP D206-642-247  
CHG002

0.00

11/24/2010

S.104.125

120



QC

Quality Control

QC4- 100% Inspect kits for completeness

0.00

Memo

INSPECT RA110121

S.104.125

11/24/2010

~

7

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

~

**Work Order ID 64120**

November 24, 2010 3:06:48 PM



Page 2

Item ID: D206-642-247

Accept



Setup Start



Revision ID:

Item Name: Wearshoe

Stop



Start Date: 11/24/10 Start Qty: 1.00



Cust Item ID:

Required Date: 11/25/10 Req'd Qty: 1.00



Customer:

Reference: RA110121

Approvals: Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/  
Work Center ID

130



Packaging

Packaging

Operation  
DescriptionSet Up/  
Run Hours

Tool ID

Tool #

Plan  
CodeAccept  
QtyReject  
QtyReject  
NumberInsp.  
Stamp

0.00

0.00

0.00

140



QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

0.00

CHG 602 AF

10/24/2010 C

CH 10/24/2010 AF

MF

10/24/2010

# Picklist Print

November 24, 2010 3:06:46 PM

Page 1

Work Order ID: 64120



Parent Item: D206-642-247



Parent Item Name: Wearshoe

Start Date: 11/24/10

Required Date: 11/25/10

Start Qty: 1.00

Required Qty: 1.00

Comments: New Issue Aug. 23/2010 DL

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D206-642-247		Manufactured	No		62031		Each	0.0000		1			

Wearshoe